

Title * O'Day-Harrison PLE-18-3.15
Culvert/Bridge Number PLE-18-3.15
Geo Location 39.712167706879214 -83.33402797579765
General Appraisal 3 Serious condition - loss of section, deterioration, or spalling have seriously affected primary structural components
Span Size 7 feet
Culvert Length 40 feet
Size of Culvert Twin 36 inch
Type Culvert Metal

Conduit

Level of Inspection X - INPSECTED FROM ENDS OF CONDUIT (NON-ENTRY)
Material 3 SERIOUS
Conduit Alignment 8 VERY GOOD
Shape 7 GOOD
Seams and Joints 6 SATISFACTORY
Slab
Abutments
Headwalls
End Structure

Channel

Channel Alignment 8 Very Good Channel has straight alignment for more than 100 feet upstream. Flow hits protective materials placed to protect conduit material.
Conduit Waterway Blockage 8 Very Good Minor amounts of sediment build-up with no appreciable loss of opening.
Scour 6 Satisfactory Minor scour holes, 1 foot or less deep, developing at inlet or outlet. Footings along the side are exposed less than 6 inches.
Channel Projection 6 Satisfactory Riprap starting to wash away. Minor erosion. Cracked concrete channel protection at inlet of a conduit.

Approaches

Pavement 6 Satisfactory Minor pavement deterioration: Minor potholes and cracking. Minor settlement.
Guardrail
Embankment 7 Good Moderate rutting from drainage; minor amount of bare soil exposed.
Comments
Owner Crews, Mark
Completed DateTime 01/16/2025 12:00:00 AM
Request Category Culvert Inspection
Group Ops-Drainage