

Title * Amity Pike CAN-36-3.18
Culvert/Bridge Number CAN-36-3.18
Geo Location 40.074399691930324 -83.23351085186006
General Appraisal 8 Very good condition - no problems noted
Span Size 8ft
Culvert Length 32ft
Size of Culvert 8x5 box
Type Culvert Concrete

Conduit

Level of Inspection M- MANNED ENTRY INSPECTION
Material 8 VERY GOOD
Conduit Alignment 9 EXCELLENT
Shape 9 EXCELLENT
Seams and Joints 8 VERY GOOD
Slab
Abutments
Headwalls 9 Excellent No signs of distress, no discoloration.
End Structure

Channel

Channel Alignment 8 Very Good Channel has straight alignment for more than 100 feet upstream. Flow hits protective materials placed to protect conduit material.
Conduit Waterway Blockage 8 Very Good Minor amounts of sediment build-up with no appreciable loss of opening.
Scour 6 Satisfactory Minor scour holes, 1 foot or less deep, developing at inlet or outlet. Footings along the side are exposed less than 6 inches.
Channel Projection 9 Excellent Embankment protection not required or in stable condition.

Approaches

Pavement 8 Very Good Hairline cracks in pavement. Minor scaling.
Guardrail 8 Very Good No noteworthy deficiencies that affect the condition of the guardrail within 50 feet of the conduit.
Embankment 8 Very Good Minor rutting from drainage; vegetation intact.
Comments Blowout to subsurface tile on inlet side.
Owner Rapp, Aaron
Completed DateTime 12/12/2024 12:00:00 AM
Request Category Culvert Inspection
Group Ops-Drainage