

**Title \*** Big Plain-Circleville FAI-4-4.45  
**Culvert/Bridge Number** FAI-4-4.45  
**Geo Location** 39.83799609550924 -83.31697180867197  
**General Appraisal** 8 Very good condition - no problems noted  
**Span Size** 8 feet  
**Culvert Length** 40 feet  
**Size of Culvert** 8x4 Box  
**Type Culvert** Concrete

### Conduit

**Level of Inspection** M- MANNED ENTRY INSPECTION  
**Material** 8 VERY GOOD  
**Conduit Alignment** 9 EXCELLENT  
**Shape** 9 EXCELLENT  
**Seams and Joints** 8 VERY GOOD

### Slab

### Abutments

**Headwalls** 8 very good Hairline cracking without rust staining or delamination(s). No dampness, leakage, or spalling. Isolated damage from construction. Minor rotation of less  
**End Structure**

### Channel

**Channel Alignment** 8 Very Good Channel has straight alignment for more than 100 feet upstream. Flow hits protective materials placed to protect conduit material.  
**Conduit Waterway Blockage** 8 Very Good Minor amounts of sediment build-up with no appreciable loss of opening.  
**Scour** 8 Very Good Minor scour holes developing at inlet or outlet. Scour protection placed.  
**Channel Projection** 8 Very Good No noteworthy deficiencies which affect the condition of the channel protection 100 feet upstream. Banks are protected or well vegetated.

### Approaches

**Pavement** 6 Satisfactory Minor pavement deterioration: Minor potholes and cracking. Minor settlement.

**Guardrail** 9 Excellent Guardrail is free from deficiencies.

**Embankment** 9 Excellent No noteworthy deficiencies which affect the condition of the embankment up to 50 feet away from the conduit.

### Comments

**Owner** Rapp, Aaron

**Completed DateTime** 01/03/2025 12:00:00 AM

**Request Category** Culvert Inspection

**Group** Ops-Drainage