

Title * David Brown MON-119-1.19
Culvert/Bridge Number MON-119-1.19
Geo Location 40.04465737667449 -83.47779698755951
General Appraisal 9 As built condition
Span Size 5 ft
Culvert Length 50 ft
Size of Culvert 5 ft
Type Culvert Plastic

Conduit

Level of Inspection M- MANNED ENTRY INSPECTION
Material 9 EXCELLENT
Conduit Alignment 9 EXCELLENT
Shape 9 EXCELLENT
Seams and Joints 9 EXCELLENT
Slab
Abutments
Headwalls
End Structure

Channel

Channel Alignment 9 Excellent Channel is flowing through conduit. No negative effects to channel protection of conduit.
Conduit Waterway Blockage 9 Excellent No blockage. Designed condition.
Scour 9 Excellent No evidence of scour at either inlet or outlet of conduit.
Channel Projection 9 Excellent Embankment protection not required or in stable condition.

Approaches

Pavement 9 Excellent No noticeable defects.
Guardrail
Embankment 9 Excellent No noteworthy deficiencies which affect the condition of the embankment up to 50 feet away from the conduit.
Comments
Owner Rapp, Aaron
Completed DateTime 11/19/2024 12:00:00 AM
Request Category Culvert Inspection
Group Ops-Drainage