

Title * Junk PLE-21-2.60
Culvert/Bridge Number PLE-21-2.60
Geo Location 39.75875941174629 -83.33044052124025
General Appraisal 9 As built condition
Span Size 60 inches
Culvert Length 40 feet
Size of Culvert 38x60
Type Culvert RCP

Conduit

Level of Inspection X - INPSECTED FROM ENDS OF CONDUIT (NON-ENTRY)
Material 9 EXCELLENT
Conduit Alignment 9 EXCELLENT
Shape 9 EXCELLENT
Seams and Joints 9 EXCELLENT
Slab
Abutments
Headwalls
End Structure

Channel

Channel Alignment 9 Excellent Channel is flowing through conduit. No negative effects to channel protection of conduit.
Conduit Waterway Blockage 9 Excellent No blockage. Designed condition.
Scour 9 Excellent No evidence of scour at either inlet or outlet of conduit.
Channel Projection 9 Excellent Embankment protection not required or in stable condition.

Approaches

Pavement 7 Good Minor problems: Raveling, hairline or map cracking. No settlement.
Guardrail
Embankment 7 Good Moderate rutting from drainage; minor amount of bare soil exposed.
Comments
Owner Rapp, Aaron
Completed DateTime 01/23/2025 12:00:00 AM
Request Category Culvert Inspection
Group Ops-Drainage