

Title * Lilly Chapel-Georgesville FAI-102-0.80
Culvert/Bridge Number FAI-102-0.80
Geo Location 39.88406324228292 -83.31351578235628
General Appraisal 8 Very good condition - no problems noted
Span Size 24 inch
Culvert Length 43 feet
Size of Culvert 24 inch
Type Culvert RCP

Conduit

Level of Inspection X - INPSECTED FROM ENDS OF CONDUIT (NON-ENTRY)
Material 9 EXCELLENT
Conduit Alignment 8 VERY GOOD
Shape 9 EXCELLENT
Seams and Joints 9 EXCELLENT

Slab

Abutments

Headwalls 8 very good Hairline cracking without rust staining or delamination(s). No dampness, leakage, or spalling. Isolated damage from construction. Minor rotation of less
End Structure

Channel

Channel Alignment 8 Very Good Channel has straight alignment for more than 100 feet upstream. Flow hits protective materials placed to protect conduit material.
Conduit Waterway Blockage 8 Very Good Minor amounts of sediment build-up with no appreciable loss of opening.
Scour 7 Good Minor scour holes developing at inlet or outlet. Top of footings is exposed. Probing indicates soft material in scour hole.
Channel Projection 8 Very Good No noteworthy deficiencies which affect the condition of the channel protection 100 feet upstream. Banks are protected or well vegetated.

Approaches

Pavement 8 Very Good Hairline cracks in pavement. Minor scaling.
Guardrail 8 Very Good No noteworthy deficiencies that affect the condition of the guardrail within 50 feet of the conduit.
Embankment 9 Excellent No noteworthy deficiencies which affect the condition of the embankment up to 50 feet away from the conduit.

Comments

Owner Rapp, Aaron
Completed DateTime 12/27/2024 12:00:00 AM
Request Category Culvert Inspection
Group Ops-Drainage