

Title * McGuire FAI-64-1.40/1.41/1.39

Culvert/Bridge Number

Geo Location 39.86502864966641 -83.30996185541154

General Appraisal 7 Good condition - some minor problems

Span Size 7 feet

Culvert Length 40 feet

Size of Culvert Triple 24 inch

Type Culvert Metal

Conduit

Level of Inspection X - INPSECTED FROM ENDS OF CONDUIT (NON-ENTRY)

Material 7 GOOD

Conduit Alignment 8 VERY GOOD

Shape 7 GOOD

Seams and Joints 7 GOOD

Slab

Abutments

Headwalls

End Structure

Channel

Channel Alignment 7 Good Silt and gravel buildup restrict half of the channel. Tree or bush growing in the channel.

Conduit Waterway Blockage 8 Very Good Minor amounts of sediment build-up with no appreciable loss of opening.

Scour 8 Very Good Minor scour holes developing at inlet or outlet. Scour protection placed.

Channel Projection 8 Very Good No noteworthy deficiencies which affect the condition of the channel protection 100 feet upstream. Banks are protected or well vegetated.

Approaches

Pavement 9 Excellent No noticeable defects.

Guardrail

Embankment 9 Excellent No noteworthy deficiencies which affect the condition of the embankment up to 50 feet away from the conduit.

Comments

Owner Rapp, Aaron

Completed DateTime 01/03/2025 12:00:00 AM

Request Category Culvert Inspection

Group Ops-Drainage