

**Title \*** Olmstead JEF-51-2.16

**Culvert/Bridge Number** JEF-51-2.16

**Geo Location** 39.915274030292494 -83.26829172670843

**General Appraisal** 6 Satisfactory condition - structural elements show some deterioration

**Span Size** 36 inch

**Culvert Length** 48 feet

**Size of Culvert** 36 inch Plastic/RCP

**Type Culvert** Concrete

### Conduit

**Level of Inspection** X - INPSECTED FROM ENDS OF CONDUIT (NON-ENTRY)

**Material** 7 GOOD

**Conduit Alignment** 8 VERY GOOD

**Shape** 7 GOOD

**Seams and Joints** 6 SATISFACTORY

**Slab**

**Abutments**

**Headwalls**

**End Structure**

### Channel

**Channel Alignment** 8 Very Good Channel has straight alignment for more than 100 feet upstream. Flow hits protective materials placed to protect conduit material.

**Conduit Waterway Blockage** 8 Very Good Minor amounts of sediment build-up with no appreciable loss of opening.

**Scour** 8 Very Good Minor scour holes developing at inlet or outlet. Scour protection placed.

**Channel Projection** 8 Very Good No noteworthy deficiencies which affect the condition of the channel protection 100 feet upstream. Banks are protected or well vegetated.

### Approaches

**Pavement** 7 Good Minor problems: Raveling, hairline or map cracking. No settlement.

**Guardrail**

**Embankment** 8 Very Good Minor rutting from drainage; vegetation intact.

**Comments** Older type of concrete pipe with shorter sections and joints that have settled and separated

**Owner** Rapp, Aaron

**Completed DateTime** 12/31/2024 12:00:00 AM

**Request Category** Culvert Inspection

**Group** Ops-Drainage