

**Title \*** Plain City-Georgesville CAN-7-8.03  
**Culvert/Bridge Number** CAN-7-8.03  
**Geo Location** 40.068014218121206 -83.25128115713596  
**General Appraisal** 9 As built condition  
**Span Size** 48 inch  
**Culvert Length** 60ft  
**Size of Culvert** 48 inch  
**Type Culvert** RCP

### Conduit

**Level of Inspection** M- MANNED ENTRY INSPECTION  
**Material** 9 EXCELLENT  
**Conduit Alignment** 9 EXCELLENT  
**Shape** 9 EXCELLENT  
**Seams and Joints** 9 EXCELLENT  
**Slab**  
**Abutments**  
**Headwalls**  
**End Structure**

### Channel

**Channel Alignment** 9 Excellent Channel is flowing through conduit. No negative effects to channel protection of conduit.  
**Conduit Waterway Blockage** 7 Good Conduit waterway blockage is less than 5% of the cross-sectional area of the opening. Bank and channel have minor amounts of drift.  
**Scour** 9 Excellent No evidence of scour at either inlet or outlet of conduit.  
**Channel Projection** 9 Excellent Embankment protection not required or in stable condition.

### Approaches

**Pavement** 9 Excellent No noticeable defects.  
**Guardrail**  
**Embankment** 9 Excellent No noteworthy deficiencies which affect the condition of the embankment up to 50 feet away from the conduit.  
**Comments** Tree needs moved at end of culvert  
**Owner** Rapp, Aaron  
**Completed DateTime** 12/11/2024 12:00:00 AM  
**Request Category** Culvert Inspection  
**Group** Ops-Drainage