

Title * Plain City-Georgesville DAR-7-9.61
Culvert/Bridge Number DAR-7-9.61
Geo Location 40.08725708231827 -83.25479686260225
General Appraisal 7 Good condition - some minor problems
Span Size 36 inches
Culvert Length 40ft
Size of Culvert 36 inches
Type Culvert Metal

Conduit

Level of Inspection X - INPSECTED FROM ENDS OF CONDUIT (NON-ENTRY)
Material 7 GOOD
Conduit Alignment 8 VERY GOOD
Shape 8 VERY GOOD
Seams and Joints 9 EXCELLENT

Slab

Abutments

Headwalls 8 very good Hairline cracking without rust staining or delamination(s). No dampness, leakage, or spalling. Isolated damage from construction. Minor rotation of less
End Structure 7 Good Hairline cracking. No crack greater than $\frac{1}{16}$ inch. Light scalingless. Delaminated and spalled area less than 1% of surface area. Grate or casting less than $\frac{1}{4}$ inch

Channel

Channel Alignment 8 Very Good Channel has straight alignment for more than 100 feet upstream. Flow hits protective materials placed to protect conduit material.
Conduit Waterway Blockage 8 Very Good Minor amounts of sediment build-up with no appreciable loss of opening.
Scour 5 Fair Minor scour holes, 2 feet or less deep, developing at inlet or outlet. Footings along the side are exposed less than 12 inches.
Channel Projection 7 Good Channel bank(s) beginning to slump. Embankment protection has minor damage. Bank protection needs minor repairs.

Approaches

Pavement 9 Excellent No noticeable defects.

Guardrail

Embankment 8 Very Good Minor rutting from drainage; vegetation intact.

Comments Blowout to subsurface tile. Culvert has light surface rust to invert.

Owner Rapp, Aaron

Completed DateTime 12/06/2024 12:00:00 AM

Request Category Culvert Inspection

Group Ops-Drainage