

**Title \*** Plain City-Georgesville JEF-7-2.15S  
**Culvert/Bridge Number** JEF-7-2.15S  
**Geo Location** 39.9825368367528 -83.26276503503323  
**General Appraisal** 9 As built condition  
**Span Size** 68inches  
**Culvert Length** 40ft  
**Size of Culvert** 68x43  
**Type Culvert** Concrete

### Conduit

**Level of Inspection** X - INPSECTED FROM ENDS OF CONDUIT (NON-ENTRY)  
**Material** 9 EXCELLENT  
**Conduit Alignment** 9 EXCELLENT  
**Shape** 9 EXCELLENT  
**Seams and Joints** 9 EXCELLENT  
**Slab**  
**Abutments**  
**Headwalls**  
**End Structure**

### Channel

**Channel Alignment** 6 Satisfactory lows through 1 of 2 pipes in multi-cell. Flows along or into one abutment or wingwall or headwall. Doesn't flow through center of the conduit  
**Conduit Waterway Blockage** 6 Satisfactory Conduit waterway blockage is less than 10% of the cross-sectional area of the opening. Sediment buildup causing flow through 1 of 2 pipes.  
**Scour** 7 Good Minor scour holes developing at inlet or outlet. Top of footings is exposed. Probing indicates soft material in scour hole.  
**Channel Projection** 9 Excellent Embankment protection not required or in stable condition.

### Approaches

**Pavement** 9 Excellent No noticeable defects.  
**Guardrail**  
**Embankment** 9 Excellent No noteworthy deficiencies which affect the condition of the embankment up to 50 feet away from the conduit.  
**Comments** Outlet needs to be in line with culvert.  
**Owner** Rapp, Aaron  
**Completed DateTime** 12/12/2024 12:00:00 AM  
**Request Category** Culvert Inspection  
**Group** Ops-Drainage