

**Title \*** Roberts Mill UNI-96-4.74  
**Culvert/Bridge Number** UNI-96-4.74  
**Geo Location** 39.90967862717598 -83.50787803530694  
**General Appraisal** 8 Very good condition - no problems noted  
**Span Size** 30 inch  
**Culvert Length** 32 feet  
**Size of Culvert** 19x30  
**Type Culvert** RCP

### Conduit

**Level of Inspection** X - INPSECTED FROM ENDS OF CONDUIT (NON-ENTRY)  
**Material** 9 EXCELLENT  
**Conduit Alignment** 8 VERY GOOD  
**Shape** 9 EXCELLENT  
**Seams and Joints** 9 EXCELLENT  
**Slab**  
**Abutments**  
**Headwalls**  
**End Structure**

### Channel

**Channel Alignment** 8 Very Good Channel has straight alignment for more than 100 feet upstream. Flow hits protective materials placed to protect conduit material.  
**Conduit Waterway Blockage** 4 Poor Conduit waterway blockage is less than 40% of the cross-sectional area of the opening. Occasional overtopping of roadway. Large deposits of debris are in the waterway.  
**Scour** 6 Satisfactory Minor scour holes, 1 foot or less deep, developing at inlet or outlet. Footings along the side are exposed less than 6 inches.  
**Channel Projection** 8 Very Good No noteworthy deficiencies which affect the condition of the channel protection 100 feet upstream. Banks are protected or well vegetated.

### Approaches

**Pavement** 6 Satisfactory Minor pavement deterioration: Minor potholes and cracking. Minor settlement.  
**Guardrail**  
**Embankment** 9 Excellent No noteworthy deficiencies which affect the condition of the embankment up to 50 feet away from the conduit.  
**Comments**  
**Owner** Rapp, Aaron  
**Completed DateTime** 01/30/2025 12:00:00 AM  
**Request Category** Culvert Inspection  
**Group** Ops-Drainage  
**Request Status** 5 - Closed