

**Title \*** Rosedale Milford Center PIK-11-6.53

**Culvert/Bridge Number** PIK-11-6.53

**Geo Location** 40.0871814618009 -83.4617781337162

**General Appraisal** 5 Fair condition - all primary structural elements are sound, but may have minor section loss

**Span Size** 58 inches

**Culvert Length** 40 ft

**Size of Culvert** 58x38

**Type Culvert** Metal

### Conduit

**Level of Inspection** M- MANNED ENTRY INSPECTION

**Material** 5 FAIR

**Conduit Alignment** 9 EXCELLENT

**Shape** 7 GOOD

**Seams and Joints** 7 GOOD

**Slab**

**Abutments**

**Headwalls**

**End Structure**

### Channel

**Channel Alignment** 8 Very Good Channel has straight alignment for more than 100 feet upstream. Flow hits protective materials placed to protect conduit material.

**Conduit Waterway Blockage** 5 Fair Conduit waterway blockage is less than 30% of the cross-sectional area of the opening. Tree or bush growing in channel. Fence placed at inlet or outlet. Rock dams in conduit.

**Scour**

**Channel Projection** 7 Good Channel bank(s) beginning to slump. Embankment protection has minor damage. Bank protection needs minor repairs.

### Approaches

**Pavement** 9 Excellent No noticeable defects.

**Guardrail**

**Embankment** 8 Very Good Minor rutting from drainage; vegetation intact.

**Comments** Invert filled with silt. Cannot inspect invert of culvert, but can visibly inspect heavy flaking rust on walls leading to invert.

**Owner** Rapp, Aaron

**Completed DateTime** 11/18/2024 12:00:00 AM

**Request Category** Culvert Inspection

**Group** Ops-Drainage