

**Title \*** Snyder Lane JEF-1117-0.70

**Culvert/Bridge Number**

**Geo Location** 39.96079432386995 -83.33605304360391

**General Appraisal** 8 Very good condition - no problems noted

**Span Size** 84 inch

**Culvert Length** 80 feet

**Size of Culvert** 84 inch

**Type Culvert** RCP

## Conduit

**Level of Inspection** M- MANNED ENTRY INSPECTION

**Material** 8 VERY GOOD

**Conduit Alignment** 9 EXCELLENT

**Shape** 9 EXCELLENT

**Seams and Joints** 8 VERY GOOD

**Slab**

**Abutments**

**Headwalls** 8 very good Hairline cracking without rust staining or delamination(s). No dampness, leakage, or spalling. Isolated damage from construction. Minor rotation of less

**End Structure**

## Channel

**Channel Alignment** 9 Excellent Channel is flowing through conduit. No negative effects to channel protection of conduit.

**Conduit Waterway Blockage** 9 Excellent No blockage. Designed condition.

**Scour** 7 Good Minor scour holes developing at inlet or outlet. Top of footings is exposed. Probing indicates soft material in scour hole.

**Channel Projection** 9 Excellent Embankment protection not required or in stable condition.

## Approaches

**Pavement** 6 Satisfactory Minor pavement deterioration: Minor potholes and cracking. Minor settlement.

**Guardrail** 4 Poor Misalignment of up to 6 posts in a row with significant settlement and rotation.

**Embankment** 9 Excellent No noteworthy deficiencies which affect the condition of the embankment up to 50 feet away from the conduit.

**Comments**

**Owner** Rapp, Aaron

**Completed DateTime** 12/26/2024 12:00:00 AM

**Request Category** Culvert Inspection

**Group** Ops-Drainage