

**Title \*** West Jefferson-Kiousville JEF-22-9.09  
**Culvert/Bridge Number** JEF-22-9.09  
**Geo Location** 39.92593586770078 -83.28633293509483  
**General Appraisal** 8 Very good condition - no problems noted  
**Span Size** 78 inches  
**Culvert Length** 48 feet  
**Size of Culvert** 78 inch  
**Type Culvert** RCP

### Conduit

**Level of Inspection** X - INPSECTED FROM ENDS OF CONDUIT (NON-ENTRY)  
**Material** 9 EXCELLENT  
**Conduit Alignment** 9 EXCELLENT  
**Shape** 9 EXCELLENT  
**Seams and Joints** 9 EXCELLENT

### Slab

### Abutments

**Headwalls** 8 very good Hairline cracking without rust staining or delamination(s). No dampness, leakage, or spalling. Isolated damage from construction. Minor rotation of less  
**End Structure**

### Channel

**Channel Alignment** 8 Very Good Channel has straight alignment for more than 100 feet upstream. Flow hits protective materials placed to protect conduit material.  
**Conduit Waterway Blockage** 8 Very Good Minor amounts of sediment build-up with no appreciable loss of opening.  
**Scour** 7 Good Minor scour holes developing at inlet or outlet. Top of footings is exposed. Probing indicates soft material in scour hole.  
**Channel Projection** 8 Very Good No noteworthy deficiencies which affect the condition of the channel protection 100 feet upstream. Banks are protected or well vegetated.

### Approaches

**Pavement** 7 Good Minor problems: Raveling, hairline or map cracking. No settlement.  
**Guardrail** 8 Very Good No noteworthy deficiencies that affect the condition of the guardrail within 50 feet of the conduit.  
**Embankment** 8 Very Good Minor rutting from drainage; vegetation intact.

### Comments

**Owner** Rapp, Aaron  
**Completed DateTime** 01/02/2025 12:00:00 AM  
**Request Category** Culvert Inspection  
**Group** Ops-Drainage