

Title * Wilson JEF-103-3.42
Culvert/Bridge Number JEF-103-3.42
Geo Location 39.919890832303686 -83.29051718115807
General Appraisal 9 As built condition
Span Size 30 inch
Culvert Length 185 feet
Size of Culvert 30 inch
Type Culvert Plastic

Conduit

Level of Inspection X - INPSECTED FROM ENDS OF CONDUIT (NON-ENTRY)
Material 9 EXCELLENT
Conduit Alignment 8 VERY GOOD
Shape 9 EXCELLENT
Seams and Joints 8 VERY GOOD
Slab
Abutments
Headwalls
End Structure

Channel

Channel Alignment 8 Very Good Channel has straight alignment for more than 100 feet upstream. Flow hits protective materials placed to protect conduit material.
Conduit Waterway Blockage 8 Very Good Minor amounts of sediment build-up with no appreciable loss of opening.
Scour 8 Very Good Minor scour holes developing at inlet or outlet. Scour protection placed.
Channel Projection 9 Excellent Embankment protection not required or in stable condition.

Approaches

Pavement 8 Very Good Hairline cracks in pavement. Minor scaling.
Guardrail
Embankment 9 Excellent No noteworthy deficiencies which affect the condition of the embankment up to 50 feet away from the conduit.
Comments Plastic under pavement with RCP ends
Owner Rapp, Aaron
Completed DateTime 12/26/2024 12:00:00 AM
Request Category Culvert Inspection
Group Ops-Drainage