

IMPROVED

Cemetery Road
MADISON CO. ROAD RECORDTownship DARBYNo. 34 - T C

Sec. _____

Shipping Point _____

Class of Traffic LIGHT

Distance _____

Built by Thos PrughDate 1917

Price \$ _____

Surveyed by A.F.L. See Field Book No. 100

BRICK	CONCRETE	SLAG—LIMESTONE	GRAVEL
Kind of foundation _____	Thickness _____	Bottom { Filler _____ Thickness } Center _____ Binder _____ Size _____	Thickness _____
Thickness of foundation _____	Kind of Cement _____		Width _____
Make of brick _____	Mixture _____	Top Course { Thickness _____ Center _____ Edge _____ Filler _____ Size _____ Binder _____	Crown _____
Width _____	Material { Gravel _____ Sink _____ Stone _____		Cu. yds. Mat. _____
Crown _____	Width _____	Binder, Method <u>Loose</u>	
Cushion _____	Crown _____	Width <u>10'</u>	
Filler _____	Kind of expansion joints } _____	Crown _____	
Kind of curb _____		Cu. yds. concrete _____	Cu. yds. Mat. _____
Size of curb <u>X</u>			
<input type="checkbox"/> yds brick _____			
Cu. yds of base _____			

GENERAL

Total length 1.70 miles.

Distance berm to berm _____

Width of R. W. _____

Distance C. to C. Ditch _____

No. of steel bridges 2

No. Con. bridges _____

No. of stone culverts 1

No. concrete culverts _____

No. of wood bridges _____

No. of C. I. P. 1

No. of cor. pipe _____

Total excavation _____

Depth of Ditches 2

Has location been changed _____

Location on R. W. _____

INSPECTION OF IMPROVED ROADS.

Date of Inspection					
BRICK					
Condition of brick					
Condition of filler					
Condition of curb					
CONCRETE					
Condition of concrete					
Condition of surface					
SLAG—LIMESTONE					
Condition of foundation					
Condition of top					
Does top need to be scarified					
Are there ruts in road					
GRAVEL					
Condition of surface					
Is road rutted					
GENERAL					
Condition of ditches					
Condition of berms					

Ref. Laid out See "Ruppell Rd." Rd. Rec No. 1, page 21

Impr. Co. 1. 0. 0. 7. Cemetery Rd. Impr. Co. Rd. Rec. No. 1, page 21