

IMPROVED

MADISON CO. ROAD RECORD

Township Canaan & Darby

No. 128

Sec. 2

Class of Traffic Medium

Shipping Point _____

Distance _____

Built by P. J. Guthrie

Date 1895

Price \$ 3970⁰⁰

Surveyed by H. L. McCafferty

BRICK	CONCRETE	SLAG—LIMESTONE	GRAVEL
Kind of foundation _____	Thickness _____	Bottom { Filler..... Center.....	Thickness <u>12"</u>
Thickness of foundation _____	Kind of Cement _____	{ Thickness } Center.....	Width <u>10 Feet</u>
Make of brick _____	Mixture _____	{ Binder Edge.....	Crown <u>6"</u>
Width _____	Material { Gravel.....	{ Thickness } Center.....	Cu. yds. Mat. <u>3814</u>
Crown _____	{ Slag Stone.....	Top Course { Filler.....	
Cushion _____	Width _____	{ Size Binder.....	
Filler _____	Crown _____	Binder, Method _____	
Kind of curb _____	Kind of expansion joints } _____	Width _____	
Size of curb <u>X</u>	Cu. yds. concrete _____	Crown _____	
<input type="checkbox"/> yds brick		Cu. yds. Mat. _____	
Cu. yds of base _____			

GENERAL

Total length 1.625 miles.
 Distance C. to C. Ditch 30'
 No. of stone culverts _____
 No. of C. I. P. V. Pipe 1
 Depth of Ditches 2'

Distance berm to berm 26'
 No. of steel bridges 1
 No. concrete culverts _____
 No. of cor. pipe C. I. P. Pipe 1
 Has location been changed _____

Width of R. W. 50
 No. Con. bridges _____
 No. of wood bridges _____
 Total excavation _____
 Location on R. W. _____

Improved Road Record 2 page 436

INSPECTION OF IMPROVED ROADS.

Date of Inspection					
BRICK					
Condition of brick					
Condition of filler					
Condition of curb					
CONCRETE					
Condition of concrete					
Condition of surface					
SLAG—LIMESTONE					
Condition of foundation					
Condition of top					
Does top need to be scarified					
Are there ruts in road					
GRAVEL					
Condition of surface					
Is road rutted					
GENERAL					
Condition of ditches					
Condition of berms					