

Grewell Road MADISON CO. ROAD RECORD

IMPROVED

Township MONROE No. 131-C

Sec. _____

Shipping Point _____

Class of Traffic _____

Distance _____

Built by _____

Date _____

Price \$ _____

Surveyed by _____

BRICK	CONCRETE..	SLAG-LIMESTONE	GRAVEL
Kind of foundation _____	Thickness _____	Bottom { Filler..... Thickness } Center..... Binder Size..... } Edge.....	Thickness _____
Thickness of foundation _____	Kind of Cement _____		Width _____
Make of brick _____	Mixture _____	Top Course { Thickness } Center..... Filler..... Size..... Binder } Edge.....	Crown _____
Width _____	Material { Gravel..... Slag..... Stone.....		Cu. yds. Mat. _____
Crown _____	Width _____	Binder, Method _____	
Cushion _____	Crown _____	Width _____	
Filler _____	Kind of } expansion joints }	Crown _____	
Kind of curb _____		Cu. yds. concrete _____	Cu. yds. Mat. _____
Size of curb <u>X</u> _____			
<input type="checkbox"/> yds brick _____			
Cu. yds of base _____			

GENERAL

Total length 1.43 miles.
 Distance C. to C. Ditch _____
 No. of stone culverts _____
 No. of C. I. P. _____
 Depth of Ditches _____

Distance berm to berm _____
 No. of steel bridges _____
 No. concrete culverts _____
 No. of cor. pipe _____
 Has location been changed _____

Width of R. W. 40'
 No. Con. bridges _____
 No. of wood bridges _____
 Total excavation _____
 Location on R. W. _____

INSPECTION OF IMPROVED ROADS.

Date of Inspection				
BRICK				
Condition of brick				
Condition of filler				
Condition of curb				
CONCRETE				
Condition of concrete				
Condition of surface				
SLAG—LIMESTONE				
Condition of foundation				
Condition of top				
Does top need to be scarified				
Are there ruts in road				
GRAVEL				
Condition of surface				
Is road rutted				
GENERAL				
Condition of ditches				
Condition of berms				

Laid out 1890. See Rd. Rec. 1 page 265
 Improved 1896 " Imp. Rec. 3 page 1